



122 MADISON  
SAN ANTONIO, TX 78210

PHONE: (210) 227-8786  
FAX: (210) 227-8030

INFO@OURKWA.ORG  
WWW.KINGWILLIAMASSOCIATION.ORG

May 2, 2016

Historic and Design Review Commission  
1901 S Alamo St  
San Antonio, Texas 78204

Re: Case #2016-2974: 203 Madison St. – *King William District*  
Certificate of Appropriateness – Front Yard Fence

Dear HDRC Commissioners,

The King William Association Architectural Advisory Committee met to review the project and concurs with the OHP staff recommendation for approval for the installation of the steel painted picket fencing with the following condition:

1. The large rock border shown along the sidewalks in the photographs was not shown on the landscape plan submitted to the OHP for administrative approval. The rock border should be eliminated. We have found instances of rocks of this size spilling out onto the sidewalk and causing tripping hazards for pedestrians.

Best Regards,

Mickey Conrad, AIA  
Chair, Architectural Advisory Committee

Harry Shafer  
President, KWA Board of Directors