



122 MADISON  
SAN ANTONIO, TX 78210

PHONE: (210) 227-8786

FAX: (210) 227-8030

INFO@OURKWA.ORG

WWW.KINGWILLIAMASSOCIATION.ORG

May 31, 2016

Historic and Design Review Commission  
1901 S Alamo St  
San Antonio, Texas 78204

Re: Case #2016-3389: 515 Mission St. – *King William Historic District*  
Certificate of Appropriateness  
1. Replace square front porch balusters.  
2. Replace rotten and damaged wood siding.

Dear HDRC Commissioners,

The King William Association Architectural Advisory Committee met to review the project and concurs with the OHP staff recommendation that the square balusters be replaced with square wood balusters to match existing.

Best Regards,

Mickey Conrad, AIA  
Chair, Architectural Advisory Committee

Harry Shafer  
President, KWA Board of Directors